



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Thursday 26th July, 2018

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following product is now obsolete **with a last-time buy date of 28th September 2018:**

- S4011-46

The following ranges/products are now obsolete **with a last-time buy date of 26th October 2018:**

- M80-752 family
- W2222-00, W2330-00, W2331-00, W2332-00, Z1001-00

The following ranges/products are now obsolete **with immediate effect:**

- Datamate S-Tek – M80-4C1xxxxS1, M80-4D1xxxxS1, M80-5C1xxxxB1, M80-5D1xxxxB1, M80-5T1xxxxB1, M80-5T2xxxxB1
- R50-300 family
- W2231-00, W2232-00, W2531-00
- Z125-925 family
- H2172-xx
- Other Special items

Please see the following spreadsheet for a detailed list of affected items:
https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2018-07-26.xlsx

Unfortunately, we are no longer able to support these product lines. Alternative items are available in some cases; please see the spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
3425-3183	Contact technical@harwin.com	Immediate	H3183-01	H3183.pdf
D01C108511C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H105586C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H107925C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H108068C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H108433C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H2172-01	H2170-H2174.pdf	Immediate	H2171-01	H2170-H2174.pdf
H2172-05	H2170-H2174.pdf	Immediate	H2171-05	H2170-H2174.pdf
HD5556	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5557	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5688	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5689	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5690	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5693	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5698	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5701	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5792	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5880-42	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5881-xx	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5917-42	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5925-10	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5930	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5934	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5940	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5941	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5942	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5943	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5964	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M106348C-SC	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-060040V0245	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-160025V3046	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-280036W0546	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-295080W0745	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20C107497CR	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-035035W0405	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-045024V1005	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-058015W0305	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-062035W0505	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-075020V1805	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-1085087	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M30C108543C-25	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-041039T2245R	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50C108942CR	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-4C10605S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-4C10642S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-4C11005S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9451002	M80-945.pdf
M80-4C11042S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9451002	M80-945.pdf
M80-4C11405S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9451402	M80-945.pdf
M80-4C11442S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9451402	M80-945.pdf
M80-4C12005S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9452002	M80-945.pdf
M80-4C12042S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9452002	M80-945.pdf
M80-4C12605S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9452602	M80-945.pdf
M80-4C12642S1	M80-4C1XXXXS1_obsolete.pdf	Immediate	M80-9452602	M80-945.pdf
M80-4D10605S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-4D10642S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-4D11005S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9451002	M80-945.pdf
M80-4D11042S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9451002	M80-945.pdf
M80-4D11405S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9451402	M80-945.pdf
M80-4D11442S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9451402	M80-945.pdf
M80-4D12005S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9452002	M80-945.pdf
M80-4D12042S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9452002	M80-945.pdf
M80-4D12605S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9452602	M80-945.pdf
M80-4D12642S1	M80-4D1XXXXS1_obsolete.pdf	Immediate	M80-9452602	M80-945.pdf
M80-5C10605B1	M80-5C1XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5C11005B1	M80-5C1XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5C11405B1	M80-5C1XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5C12005B1	M80-5C1XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5C12605B1	M80-5C1XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5D10605B1	M80-5D1XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5D11005B1	M80-5D1XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-5D11405B1	M80-5D1XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5D12005B1	M80-5D1XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5D12605B1	M80-5D1XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5T10605B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5T10622B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5T10642B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5T11005B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5T11022B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5T11042B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5T11405B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5T11422B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5T11442B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5T12005B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5T12022B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5T12042B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5T12605B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5T12622B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5T12642B1	M80-5T1XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5T20605B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5T20622B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5T20642B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	Contact technical@harwin.com	
M80-5T21005B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5T21022B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5T21042B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9061002	M80-906.pdf
M80-5T21405B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5T21422B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5T21442B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9061402	M80-906.pdf
M80-5T22005B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5T22022B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5T22042B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9062002	M80-906.pdf
M80-5T22605B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5T22622B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-5T22642B1	M80-5T2XXXXB1_obsolete.pdf	Immediate	M80-9062602	M80-906.pdf
M80-7520242	M80-752_obsolete.pdf	26th October 2018	M80-7820242	M80-782.pdf
M80-7520322	M80-752_obsolete.pdf	26th October 2018	M80-7820342	M80-782.pdf
M80-7520422	M80-752_obsolete.pdf	26th October 2018	M80-7820442	M80-782.pdf
M80-7520522	M80-752_obsolete.pdf	26th October 2018	M80-7820542	M80-782.pdf
M80-7520542	M80-752_obsolete.pdf	26th October 2018	M80-7820542	M80-782.pdf
M80-7520622	M80-752_obsolete.pdf	26th October 2018	M80-7820642	M80-782.pdf
M80-7520642	M80-752_obsolete.pdf	26th October 2018	M80-7820642	M80-782.pdf
M80-7520722	M80-752_obsolete.pdf	26th October 2018	M80-7820742	M80-782.pdf
M80-7520742	M80-752_obsolete.pdf	26th October 2018	M80-7820742	M80-782.pdf
M80-7521722	M80-752_obsolete.pdf	26th October 2018	M80-7821742	M80-782.pdf
M80-7521742	M80-752_obsolete.pdf	26th October 2018	M80-7821742	M80-782.pdf
M80-7522222	M80-752_obsolete.pdf	26th October 2018	M80-7822242	M80-782.pdf
M80-7522242	M80-752_obsolete.pdf	26th October 2018	M80-7822242	M80-782.pdf
M80C108780C-2242	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108963C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108964C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90-7010845	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109334C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109335C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109337C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109338C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C150626C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C150627C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
R50-3000802	R50-300_obsolete.pdf	Immediate	R40-3000802	R40-300.pdf
R50-3000902	R50-300_obsolete.pdf	Immediate	R40-3000902	R40-300.pdf
R50-3001002	R50-300_obsolete.pdf	Immediate	R40-3001002	R40-300.pdf
R50-3001102	R50-300_obsolete.pdf	Immediate	R40-3001102	R40-300.pdf
R50-3001202	R50-300_obsolete.pdf	Immediate	R40-3001202	R40-300.pdf
R50-3001302	R50-300_obsolete.pdf	Immediate	R40-3001302	R40-300.pdf
R50-3001402	R50-300_obsolete.pdf	Immediate	R40-3001402	R40-300.pdf
R50-3001502	R50-300_obsolete.pdf	Immediate	R40-3001502	R40-300.pdf
R50-3001602	R50-300_obsolete.pdf	Immediate	R40-3001602	R40-300.pdf
R50-3001802	R50-300_obsolete.pdf	Immediate	R40-3001802	R40-300.pdf
R50-3002002	R50-300_obsolete.pdf	Immediate	R40-3002002	R40-300.pdf
R50-3002502	R50-300_obsolete.pdf	Immediate	R40-3002502	R40-300.pdf
R50-3003002	R50-300_obsolete.pdf	Immediate	R40-3003002	R40-300.pdf
R50-3003502	R50-300_obsolete.pdf	Immediate	R40-3003502	R40-300.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
R50-3004002	R50-300_obsolete.pdf	Immediate	R40-3003502	R40-300.pdf
R50-3005002	R50-300_obsolete.pdf	Immediate	R40-3003502	R40-300.pdf
S4011-46	S4011_obsolete.pdf	28th September 2018	Contact technical@harwin.com	
W2222-00	W2222_obsolete.pdf	26th October 2018	Contact technical@harwin.com	
W2231-00	W2231_obsolete.pdf	Immediate	Contact technical@harwin.com	
W2232-00	W2232_obsolete.pdf	Immediate	Contact technical@harwin.com	
W2330-00	W2330_obsolete.pdf	26th October 2018	Contact technical@harwin.com	
W2331-00	W2331_obsolete.pdf	26th October 2018	Contact technical@harwin.com	
W2332-00	W2332_obsolete.pdf	26th October 2018	Contact technical@harwin.com	
W2531-00	W2531_obsolete.pdf	Immediate	Contact technical@harwin.com	
Z1001-00	Z1001_obsolete.pdf	26th October 2018	Contact technical@harwin.com	
Z125-9250600	Contact technical@harwin.com	Immediate	Z125-9260600	Z125-926.pdf
Z125-9251000	Contact technical@harwin.com	Immediate	Z125-9261000	Z125-926.pdf
Z125-9251200	Contact technical@harwin.com	Immediate	Z125-9261200	Z125-926.pdf
Z125-9251600	Contact technical@harwin.com	Immediate	Z125-9261600	Z125-926.pdf
Z125-9252000	Contact technical@harwin.com	Immediate	Z125-9262000	Z125-926.pdf
Z125-9252600	Contact technical@harwin.com	Immediate	Z125-9262600	Z125-926.pdf
Z125-9253400	Contact technical@harwin.com	Immediate	Z125-9263400	Z125-926.pdf
Z125-9255000	Contact technical@harwin.com	Immediate	Z125-9265000	Z125-926.pdf