



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Tuesday 21st April, 2020

Dear Customer,

Re: Obsolescence notification for Harwin product.

The following items are now obsolete **with a Last-Time Buy date of 21st August 2020**. Pin counts of **17 and 22 ONLY** are obsolete from the following ranges (**NOT the complete range**):

- M80-782
- M80-792
- M80-842
- M80-843
- M80-852
- M80-882

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_21-Apr-2020.xlsx

Unfortunately, after these dates and upon exhaustion of stock, we are no longer able to support these product lines. Alternative items may be available in some cases; please see the spreadsheet for the alternative part numbers where applicable. The website will be updated as soon as possible.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-7821722	M80-782.pdf	21st August 2020	M80-8771722	M80-877.pdf
M80-7821742	M80-782.pdf	21st August 2020	M80-8771722	M80-877.pdf
M80-7821745	M80-782.pdf	21st August 2020	M80-8771705	M80-877.pdf
M80-7822222	M80-782.pdf	21st August 2020	M80-8772222	M80-877.pdf
M80-7822242	M80-782.pdf	21st August 2020	M80-8772222	M80-877.pdf
M80-7822245	M80-782.pdf	21st August 2020	M80-8772205	M80-877.pdf
M80-7921722	M80-792.pdf	21st August 2020	M80-8761722	M80-876.pdf
M80-7921742	M80-792.pdf	21st August 2020	M80-8761722	M80-876.pdf
M80-7921745	M80-792.pdf	21st August 2020	M80-8761705	M80-876.pdf
M80-7922222	M80-792.pdf	21st August 2020	M80-8762222	M80-876.pdf
M80-7922242	M80-792.pdf	21st August 2020	M80-8762222	M80-876.pdf
M80-7922245	M80-792.pdf	21st August 2020	M80-8762205	M80-876.pdf
M80-8421722	M80-842.pdf	21st August 2020	M80-8761722	M80-876.pdf
M80-8421742	M80-842.pdf	21st August 2020	M80-8761722	M80-876.pdf
M80-8421745	M80-842.pdf	21st August 2020	M80-8761705	M80-876.pdf
M80-8422222	M80-842.pdf	21st August 2020	M80-8762222	M80-876.pdf
M80-8422242	M80-842.pdf	21st August 2020	M80-8762222	M80-876.pdf
M80-8422245	M80-842.pdf	21st August 2020	M80-8762205	M80-876.pdf
M80-8431722	M80-843.pdf	21st August 2020	M80-8781722	M80-878.pdf
M80-8431742	M80-843.pdf	21st August 2020	M80-8781722	M80-878.pdf
M80-8431745	M80-843.pdf	21st August 2020	M80-8781705	M80-878.pdf
M80-8432222	M80-843.pdf	21st August 2020	M80-8782222	M80-878.pdf
M80-8432242	M80-843.pdf	21st August 2020	M80-8782222	M80-878.pdf
M80-8432245	M80-843.pdf	21st August 2020	M80-8782205	M80-878.pdf
M80-8521722	M80-852.pdf	21st August 2020	M80-8791722	M80-879.pdf
M80-8521742	M80-852.pdf	21st August 2020	M80-8791722	M80-879.pdf
M80-8521745	M80-852.pdf	21st August 2020	M80-8791705	M80-879.pdf
M80-8522222	M80-852.pdf	21st August 2020	M80-8792222	M80-879.pdf
M80-8522242	M80-852.pdf	21st August 2020	M80-8792222	M80-879.pdf
M80-8522245	M80-852.pdf	21st August 2020	M80-8792205	M80-879.pdf
M80-8821722	M80-882.pdf	21st August 2020	M80-8771722	M80-877.pdf
M80-8821742	M80-882.pdf	21st August 2020	M80-8771722	M80-877.pdf
M80-8821745	M80-882.pdf	21st August 2020	M80-8771705	M80-877.pdf
M80-8822222	M80-882.pdf	21st August 2020	M80-8772222	M80-877.pdf
M80-8822242	M80-882.pdf	21st August 2020	M80-8772222	M80-877.pdf
M80-8822245	M80-882.pdf	21st August 2020	M80-8772205	M80-877.pdf