

Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451

Monday 7<sup>th</sup> March 2022

Dear Customer,

**Re: Product Change notification for Harwin product.**

Please be advised that the male horizontal connectors in the M83 Series (Datamate 3-Row Jackscrew) have had the nominal dimension on the termination/tail length changed on the applicable Technical Drawings. The length has changed from (4.0mm) to (3.5 +0.6/-0.5mm).

This change has been made so that the drawings accurately accommodate the tolerance of the individual components. No changes have been made to the actual production process.

The parts affected include:

- M83-LML3M1Nxx-0000-000
- M83-LML3M5N18-0000-000
- M83-LML3M7N18-0000-000
- M83-LML3M5N13-0302-333
- M83-LML3M5N19-0101-333

Please see the following spreadsheet for a detailed list of affected items:

[https://cdn.harwin.com/pdfs/PCN\\_spreadsheet\\_2022-03-07.xlsx](https://cdn.harwin.com/pdfs/PCN_spreadsheet_2022-03-07.xlsx)

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team  
[technical@harwin.com](mailto:technical@harwin.com)

# Product Change Notification from Harwin

Part number affected	Drawing for affected product
M83-LML3M1N18-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M1N27-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M1N36-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M1N48-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M1N54-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M1N60-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M1N96-0000-000	<a href="#">M83-LML3M1NXX-0000-000.pdf</a>
M83-LML3M5N18-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N27-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N36-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N48-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N54-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N60-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N96-0000-000	<a href="#">M83-LML3M5NXX-0000-000.pdf</a>
M83-LML3M5N13-0302-333	<a href="#">M83-LML3M5N13-0302-333.pdf</a>
M83-LML3M5N19-0101-333	<a href="#">M83-LML3M5N19-0101-333.pdf</a>
M83-LML3M7N18-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>
M83-LML3M7N27-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>
M83-LML3M7N36-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>
M83-LML3M7N48-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>
M83-LML3M7N54-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>
M83-LML3M7N60-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>
M83-LML3M7N96-0000-000	<a href="#">M83-LML3M7NXX-0000-000.pdf</a>