



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Monday 9th April, 2018

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete. These items have a **Last Time Buy date of 6th July 2018:**

- M80-5T106M3-04-331
- M80-8181022R
- M80-8182022P
- M80-8182022R

These items have **no Last Time Buy date**, and are obsolete with immediate effect:

- S1721-46
- M80-4C100F1-40-000, M80-4C110F1-21-325-305, M80-4C120F1-20-325, M80-4T210F1-12-302, M80-5L100M1-40-333, M80-5L100M4-40-313, M80-5L210M1-21-334-314, M80-5L220M1-20-334, M80-5T104M1-22-311, M80-5T12400-60-331
- M80-720 series, M80-722 series, M80-746 series, M80-749 series, M80-750 series, M80-818 series (other than those listed above), M80-847 series, M80-849 series, M80-860 series, M80-861 series, M80-870 series, M80-871 series, M80-872 series, M80-873 series, M80-874 series, M80-892 series, M80-950 series, M80-960 series, M80-965 series
- Various export controlled customer special products

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_Harwin_Products_09_April_2018.xlsx

Unfortunately, we are no longer able to support these product lines. Alternative items are available in some cases; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-8181222P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8181422P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8181622P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8181822P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8182022P	Contact technical@harwin.com	6th July 2018	Contact technical@harwin.com	
M80-8182022R	Contact technical@harwin.com	6th July 2018	Contact technical@harwin.com	
M80-8182622P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8183422P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8183422R	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-8184422P	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-847 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-849 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-860 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-861 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-870 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-871 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-872 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-873 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-874 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-892 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-950 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-960 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-965 - all items	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0004	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0005	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0006	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0007	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0008	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0009	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0010	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0011	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0012	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
159D5922P0014	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
342A9761P22	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
356A7435P0002	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
717405611-002	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
717405611-011	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0002	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0003	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0004	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0005	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0006	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0009	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0010	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0011	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
7591041P0014	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HDL159D5922P0002	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HDL356A7435P1	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HDL7591041P0004	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M106917C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50C107412C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	