



Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451

Friday 21<sup>st</sup> October, 2022

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

Please be advised that the following part numbers are now obsolete with immediate effect.

- M40-620xx46
- **NOTE: M40-620xx46R are not affected, and are still available**

Please see the following spreadsheet for a detailed list of affected items:  
[https://cdn.harwin.com/pdfs/Obsolescence\\_notification\\_spreadsheet\\_2022-10-21.xlsx](https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2022-10-21.xlsx)

Unfortunately, we are no longer able to support this packing variation on these product ranges. Alternative items are available; please see the attached list for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team  
[technical@harwin.com](mailto:technical@harwin.com)