



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Monday 26th October, 2020

Dear Customer,

Re: Product Change Notification for Harwin product.

This PCN relates to the following part numbers:

- M50-3610542
- M50-3610642
- M50-3610742
- M50-3610842
- M50-3611042
- M50-3611242
- M50-3611542
- M50-3612042
- M50-3612542
- M50-3610542R
- M50-3610642R
- M50-3610742R
- M50-3610842R
- M50-3611042R
- M50-3612042R
- M50-3612542R

Minor changes have been made to the following dimensions/features:

- Cutting v-grooves on the housing (between pins) are removed
- Location peg size reduced from Ø0.75mm to Ø0.70mm
- Recommended PCB holes for the location pegs increased from Ø0.80mm to Ø0.95mm
- Recommended SMT pad dimensions changed from 2.50 x 0.65mm to 2.62 x 0.80mm

You should be able to use any existing PCBs or product without alteration to your current PCB layout. If you experience any issues, do please feel free to contact us for advice.

Unfortunately, we are no longer able to support the previous design.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com